

COMMISSIONER'S MONTHLY REPORT

Commissioner

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

Date July 31

1967

Report for Month of June

1967

Source and Point of Measurement	Day of the Month											
	1	2	3	4	5	6	7	8	9	10	11	12
	16	17	18	19	20	21	22	23	24	25	26	27
I. Boardman Springs												
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)							*	8:30 AM Top of well				9:00 AM Over top of well
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. water)							*	Flowing				4.7
#3. Church ditch near to heading												—
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)								1.79				0.371
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake							*	2.09				1.15
II. Thomas Spring												
#5. Above the Olsen house below the tracks								9.48				0.966
III. Drain												
#6. Drain Channel near Railroad Shop and Burningham properties								1.66				1.535
IV. #8. Levie Ditch - Water to Church Farm, etc.							*	1.0				0.5
V. #9. Pump Water at Church Welfare Farm								5.73				0.30
								0.0				0.0

For key to location numbers see drawing P-5107

Submitted by

E. Lewis Allen

\* Extra from Storms